

CoB: Colrain stony fine sandy loam, 3 to 8 percent slopes

The Colrain component makes up 85 percent of the map unit. The natural drainage class is well drained. Water movement in the most restrictive layer is high. This component is on hills on glaciated uplands. The parent material consists of coarse-loamy till. Depth to a root restrictive layer is greater than 60 inches.

Important farmland classification: Prime	Land capability: 2 e	Vermont Agricultural Value Group: 3
--	----------------------	-------------------------------------

Vermont Residential Onsite Waste Disposal Group and Subgroup: Ic

This unit is well suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. With moderate permeability and slopes less than 20 percent, there are few limitations.

PHYSICAL and CHEMICAL PROPERTIES							EROSION FACTORS		
Soil name	Depth (In)	Typical texture	Clay (Pct)	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	Kw	Kf	T
Colrain	0-6	FSL	3-7	5.1 - 7.3	2-6	2.0-8.0	.24	.24	5
	6-33	FSL	3-7	5.1 - 7.3	2-6	0.5-3.0	.32	.32	
	33-60	FSL	3-7	5.6 - 7.3	2-6	0.0-1.0	.43	.43	

WATER FEATURES						SOIL FEATURES		
Soil name	Hydrologic group	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric soil?	Depth to bedrock (range in inches)
			Frequency	Duration	Frequency	Duration		
Colrain	A	---	None		None		No	---

LAND USE LIMITATIONS				AGRICULTURAL YIELD DATA	
Soil name	Land use	Rating	Reason **	Crop name	Yield / acre
Colrain	Dwellings with basements:	Not limited		Grass-legume hay	4.5 Tons
Colrain	Pond reservoir areas:	Very limited	Seepage	Grass-clover	7.2 AUM
				Grass hay	4.5 Tons
				Corn silage	22 Tons
				Alfalfa hay	5 Tons

WOODLAND MANAGEMENT				
Soil name	Management concern	Rating	Reason	Vermont natural communities
Colrain	Harvest equip operability:	Well suited		Northern Hardwood Forest, Mesic Red Oak-Northern Hardwood Forest, Mesic Maple-Ash-Hickory-Oak Forest
Colrain	Road suitability:	Well suited		
Colrain	Erosion hazard (off-road):	Slight		