

## HdE: Hartland silt loam, 25 to 50 percent slopes

The Hartland component makes up 85 percent of the map unit. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. This component is on dissected terraces on lake plains. The parent material consists of coarse-silty glaciolacustrine deposits. Depth to a root restrictive layer is greater than 60 inches.

## Vermont Residential Onsite Waste Disposal Group and Subgroup: IVd

This unit is generally not suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. Steep slopes in association with the slowly permeable substratum is the limiting condition. Cut and fill site modifications that reduce the slope gradient are not generally effective due to the slowly permeable substratum.

PHYSICAL and CHEMICAL PROPERTIES								EROSION FACTORS	
Soil name	Depth (In)	Typical texture	Clay (Pct)	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	<u>EROSION I ACTORS</u>		
							Kw	Kf	Т
Hartland	0-6	SIL	3-10	5.1 - 7.8	0.6-2	2.0-8.0	.43	.43	5
	6-19	SIL	3-10	5.1 - 7.8	0.6-2	0.5-3.0	.55	.55	
	19-60	SI	3-16	5.1 - 7.8	0.2-2	0.0-1.0	.64	.64	

WATER FEATURES							SOIL FEATURES		
Soil name	Hydrologic group	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric		
			Frequency	Duration	Frequency	Duration	soil?	Depth to bedrock (range in inches)	
Hartland	В		None		None		No		

	LAND USE LIMITAT	<u>AG</u>	AGRICULTURAL YIELD DATA			
Soil name	Land use	Rating	Reason **	Crop	name	Yield / acre
Hartland	Dwellings with basements:	Very limited	Slope			
Hartland	Pond reservoir areas:	Very limited	Slope			

	Management		WOODLAND MANAGI	EMENT
Soil name	concern	Rating Reason		Vermont natural communities
Hartland	Harvest equip operability:	Poorly suited	Slope	Northern Hardwood Forest,
Hartland	Road suitability:	Poorly suited	Slope	Mesic Maple-Ash-Hickory-Oak Forest, Rich Northern Hardwood Forest
Hartland	Erosion hazard (off-road):	Severe	Slope/erodibility	Non Northern Hardwood Folest