

## 31E: Paxton fine sandy loam, 25 to 35 percent slopes, very stony

The Paxton component makes up 80 percent of the map unit. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. This component is on ridges on glaciated uplands, hills on glaciated uplands. The parent material consists of coarse-loamy basal till. Depth to a root restrictive layer, densic material, is 20 to 38 inches.

## Vermont Residential Onsite Waste Disposal Group and Subgroup: IVd

This unit is generally not suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. Steep slopes in association with the slowly permeable substratum is the limiting condition. Cut and fill site modifications that reduce the slope gradient are not generally effective due to the slowly permeable substratum.

PHYSICAL and CHEMICAL PROPERTIES								EROSION FACTORS	
Soil name	Depth (In)	Typical texture	Clay (Pct)	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	<u>LICOSON I ACTORO</u>		
							Kw	Kf	Т
Paxton	0-7	FSL	3-12	4.5 - 6.0	0.6-2	2.0-5.0	.24	.24	3
	7-26	FSL	3-12	4.5 - 6.0	0.6-2	0.5-3.0	.32	.32	
	26-60	FSL	3-12	4.5 - 6.0	0-0.2	0.5-3.0	.37	.37	

WATER FEATURES							SOIL FEATURES		
Soil name	Hydrologic group	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric		
			Frequency	Duration	Frequency	Duration	soil?	Depth to bedrock (range in inches)	
Paxton	С	1.5-2.5	None		None		No		

	LAND USE LIMITAT	AGRICULTUR	AGRICULTURAL YIELD DATA			
Soil name	Land use	Rating	Reason **	Crop name	Yield / acre	
Paxton	Dwellings with basements:	Very limited	Slope	-		
Paxton	Pond reservoir areas:	Very limited	Slope			

	Management	WOODLAND MANAGEMENT			
Soil name	concern	Rating	Reason	Vermont natural communities	
Paxton	Harvest equip operability:	Moderately suited	Slope	Mesic Maple-Ash-Hickory-Oak Forest,	
Paxton	Road suitability:	Poorly suited	Slope	Northern Hardwood Forest	
Paxton	Erosion hazard (off-road):	Moderate	Slope/erodibility		