

41E: Buxton silt loam, 25 to 45 percent slopes

The Buxton component makes up 85 percent of the map unit. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is very low. This component is on dissected lake plains, lake plains. The parent material consists of clayey glaciolacustrine deposits. Depth to a root restrictive layer is greater than 60 inches.

Vermont Residential Onsite Waste Disposal Group and Subgroup: IVd

This unit is generally not suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. Steep slopes in association with the slowly permeable substratum is the limiting condition. Cut and fill site modifications that reduce the slope gradient are not generally effective due to the slowly permeable substratum.

		PHYSICAL and	HEMICAL	PROPERT	<u>IES</u>		EDOS	ION E	ACTORS
Soil name	Depth	Typical	Clay	Soil reaction	Permeability (In/Hr)	Organic matter	ERUS	NON F	ACTORS
Contraine	(ln)	texture	(Pct)	(pH)	(117111)	(Pct)	Kw	Kf	Т
Buxton	0-1	SPM		3.2 - 5.7	2-6	25-95			5
	1-3	SIL	20-60	5.1 - 6.5	0.2-2	3.0-8.0	.32	.32	
	3-13	SIL	20-60	5.6 - 7.3	0.06-0.6	0.5-3.0	.43	.43	
	13-26	SICL	30-60	5.6 - 7.3	0.001-0.2	0.0-1.0	.43	.43	
	26-66	SIC	30-60	5.6 - 7.3	0.001-0.2	0.0-0.5	.32	.32	
		WATE	R FEATURES	<u>s</u>				SOIL	FEATURES
	Hydrologic	Depth to seasonal	Flooding		Ponding		Hv	dric	
Soil name	group	high water table (Feet)	Frequency	Duration	Frequency	Duration		oil?	Depth to bedrock (range in inches
Buxton	D	1.5-3.0	None		None			No	

	LAND USE LIMITA	AGRICULTURAL YIELD DATA		
Soil name	Land use	Rating	Reason **	Crop name Yield / ac
Buxton Dwellings with basements:		Very limited	Slope	•
Buxton	Pond reservoir areas:	Very limited	Slope	
	Management	<u>v</u>	VOODLAND MANAGE	MENT
Soil name	concern	Rating	Reason	Vermont natural communities
Buxton	Harvest equip operability:	Poorly suited	Slope	Northern Hardwood Forest,
	D 1 2 1 22	Poorly suited	Slope	Red Spruce-Northern Hardwood Fores
Buxton	Road suitability:	Foorly Suited	Olope	