

36D: Teago-Pomfret complex, 15 to 25 percent slopes, rocky

The Teago, rocky component makes up 60 percent of the map unit. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is low. This component is on moderately steep hills on glaciated uplands. The parent material consists of sandy till. Depth to a root restrictive layer, bedrock, lithic, is 20 to 40 inches.

The Pomfret, rocky component makes up 25 percent of the map unit. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. This component is on moderately steep hills on glaciated uplands. The parent material consists of sandy till. Depth to a root restrictive layer, bedrock, lithic, is 40 to 96 inches.

Important farmland classification: NPSL	Land capability: 4 e	Vermont Agricultural Value Group: 8
---	----------------------	-------------------------------------

Vermont Residential Onsite Waste Disposal Group and Subgroup: IId

This unit is moderately suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. The depth to bedrock and slopes greater than 20 percent in some areas are the primary concerns. A significant percentage of this map unit has sufficient soil depth over bedrock to accept a range of designs. On-site investigations can help avoid areas with limited depth to bedrock. Additional fill material may be needed in some areas in order to meet the separation distance requirement between the bottom of the leachfield and bedrock. There may be less-sloping areas within the unit that are suitable for siting a septic system, or, if feasible, cut and fill site modifications may produce an acceptable area within the unit. An erosion prevention and sediment control plan is required by the State for construction on sites over 20 percent slope.

PHYSICAL and CHEMICAL PROPERTIES								EROSION FACTORS	
Soil name	Depth	Typical	Clay (Pct)	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	EROSION FACTORS		
	(ln)	texture					Kw	Kf	Т
Teago, rocky	0-5	FSL	1-7	5.1 - 6.5	2-20	2.0-8.0	.24	.24	2
	5-23	LFS	0-7	5.1 - 6.5	2-20	1.0-3.0	.20	.20	
	23-32	CN-S	0-5	6.1 - 7.3	6-20	0.0-2.0	.05	.10	
	32-42	UWB			0.01-20				
Pomfret, rocky	0-11	LFS	1-7	5.6 - 7.3	2-20	2.0-8.0	.15	.15	5
	11-34	LFS	1-7	5.6 - 7.3	2-20	0.5-3.0	.28	.28	
	34-61	FS	0-5	6.1 - 7.3	6-20	0.0-1.0	.10	.10	
	61-71	UWB			0.01-20				

WATER FEATURES							SOIL FEATURES		
	Hydrologic	high water table	Flooding		Ponding		Hydric		
Soil name	group		Frequency	Duration	Frequency	Duration	soil?	Depth to bedrock (range in inches)	
Teago, rocky	А		None		None		No	20-40	
Pomfret, rocky	Α		None		None		No	40-96	

	LAND USE LIMITA	<u>AGRICULTURA</u>	L YIELD DATA		
Soil name	Land use	Rating	Reason **	Crop name	Yield / acre
Pomfret, rocky	Dwellings with basements:	Very limited	Slope	Pasture	4 AUM
Teago, rocky	Dwellings with basements:	Very limited	Slope	Grass hay	2.5 Tons
	ŭ	,	·	Alfalfa hay	2.5 Tons
Pomfret, rocky	Pond reservoir areas:	Very limited	Seepage	Pasture	4 AUM
Teago, rocky	Pond reservoir areas:	Very limited	Seepage	Grass hay	2.5 Tons
				Alfalfa hay	3 Tons

	Management	<u>w</u>	OODLAND M	ANAGEMENT
Soil name	concern	Rating	Reason	Vermont natural communities
Pomfret	Harvest equip operability:	Moderately suited	Slope	Northern Hardwood Forest,
Teago	Harvest equip operability:	Moderately suited	Slope	Mesic Red Oak-Northern Hardwood Forest, Rich Northern Hardwood Forest
Pomfret	Road suitability:	Poorly suited	Slope	Nonvoluem Haldwood Folest



Soil Fact Sheet - Continued

Windsor County, Vermont

Teago Road suitability: Poorly suited Slope

Pomfret Erosion hazard (off-road): Moderate Slope/erodibility
Teago Erosion hazard (off-road): Moderate Slope/erodibility