

## FmD: Farmington-Rock outcrop complex, 15 to 60 percent slopes

The Farmington component makes up 45 percent of the map unit. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is low. This component is on ridges on glaciated uplands. The parent material consists of coarse-loamy till. Depth to a root restrictive layer, bedrock, lithic, is 10 to 20 inches.

The Rock outcrop component makes up 40 percent of the map unit. Water movement in the most restrictive layer is low. This component is on ridges on glaciated uplands. Depth to a root restrictive layer0 inches, bedrock, lithic..

Important farmland classification: NPSL	Land capability: 7 e	Vermont Agricultural Value Group: 11
---	----------------------	--------------------------------------

## Vermont Residential Onsite Waste Disposal Group and Subgroup: IVc

This unit is generally not suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. The very shallow to shallow depth to bedrock is the limiting condition.

PHYSICAL and CHEMICAL PROPERTIES							EROSION FACTORS		
Soil name	Depth	Typical	Clay (Pct)	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	EROSION I ACTORS		
	(ln)	(In) texture					Kw	Kf	Т
Farmington	0-4	L	10-27	5.1 - 7.3	0.6-2	2.0-6.0	.32	.32	1
•	4-14	L	10-27	5.6 - 7.8	0.6-2	0.0-1.0	.49	.49	
	14-24	UWB			0.01-20				
Rock outcrop	0-60	UWB			0.01-20				

WATER FEATURES							SOIL FEATURES		
Soil name	Hydrologic group	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric		
			Frequency	Duration	Frequency	Duration	soil?	Depth to bedrock (range in inches)	
Farmington	D		None		None		No	10-20	
Rock outcrop			None				Unranked	I 0	

	LAND USE LIMITAT	AGRICULTURAL YIELD DATA			
Soil name	Land use	Rating	Reason **	Crop name	Yield / acre
Farmington	Dwellings with basements:	Very limited	Slope		
Farmington	Pond reservoir areas:	Very limited	Slope		
			V000LAND MANAGEMENT		
	Managament	<u>v</u>	VOODLAND MANAGEMENT		

	Management		<u>EMENT</u>	
Soil name	concern	Rating	Reason	Vermont natural communities
Farmington	Harvest equip operability:	Poorly suited	Slope	Mesic Maple-Ash-Hickory-Oak Forest,
Farmington	Road suitability:	Poorly suited	Slope	Transition Hardwoods Limestone Forest Variant, Limestone Bluff Cedar-Pine Forest,
Farmington	Erosion hazard (off-road):	Severe	Slope/erodibility	Temperate Calcareous Outcrop, Northern Hardwoods Limestone Forest Variant, Temperate Calcareous Cliff, Boreal Calcareous Cliff