

19D: Vershire-Dummerston complex, 15 to 25 percent slopes, rocky

The Vershire, rocky component makes up 60 percent of the map unit. The natural drainage class is well drained. Water movement in the most restrictive layer is low. This component is on moderately steep hills on glaciated uplands. The parent material consists of loamy till. Depth to a root restrictive layer, bedrock, lithic, is 20 to 40 inches.

The Dummerston, rocky component makes up 25 percent of the map unit. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. This component is on moderately steep hills on glaciated uplands. The parent material consists of loamy till. Depth to a root restrictive layer is greater than 60 inches.

Important farmland classification:	NPSL	Land capability: 4 e	Vermont Agricultural Value Group: 8
------------------------------------	------	----------------------	-------------------------------------

Vermont Residential Onsite Waste Disposal Group and Subgroup: IId

This unit is moderately suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. The depth to bedrock and slopes greater than 20 percent in some areas are the primary concerns. A significant percentage of this map unit has sufficient soil depth over bedrock to accept a range of designs. On-site investigations can help avoid areas with limited depth to bedrock. Additional fill material may be needed in some areas in order to meet the separation distance requirement between the bottom of the leachfield and bedrock. There may be less-sloping areas within the unit that are suitable for siting a septic system, or, if feasible, cut and fill site modifications may produce an acceptable area within the unit. An erosion prevention and sediment control plan is required by the State for construction on sites over 20 percent slope.

PHYSICAL and CHEMICAL PROPERTIES EROSION F									CTORS
Soil name	Depth	Typical	Clay	Soil	Permeability	Organic	EROSION FACTORS		
Soil Harrie	(ln)	texture	(Pct)	reaction (In/Hr) (pH)	matter (Pct)	Kw	Kf	Т	
Vershire, rocky	0-5	FSL	4-18	4.5 - 6.5	0.6-2	1.0-4.0	.20	.20	2
	5-26	CN-FSL	4-18	4.5 - 6.5	0.6-2	0.5-3.0	.17	.28	
	26-36	UWB			0.01-20				
Dummerston, rocky	0-5	FSL	2-10	4.5 - 6.0	0.6-2	2.0-4.0	.32	.32	5
	5-21	FSL	2-10	4.5 - 6.0	0.6-2	0.5-3.0	.43	.43	
	21-65	FSL	2-10	4.5 - 6.0	0.6-2	0.0-1.0	.49	.49	

WATER FEATURES							SOIL FEATURES		
Soil name	Hydrologic	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric		
	group		Frequency	Duration	Frequency	Duration	soil?	Depth to bedrock (range in inches)	
Vershire, rocky	С		None		None		No	20-40	
Dummerston, rocky	В		None		None		No		

LAND USE LIMITATIONS					AGRICULTURAL YIE	ELD DATA
Soil name	Land use	Rating	Reason **	Cr	rop name	Yield / acre
Vershire, rocky	Dwellings with basements:	Very limited	Slope		Grass-legume hay	3 Tons
Dummerston, rocky	Dwellings with basements:	Very limited	Slope		Grass-clover Grass hay	4.8 AUM 3 Tons
Vershire, rocky Dummerston, rocky	Pond reservoir areas: Pond reservoir areas:	Very limited Very limited	Slope Slope		Corn silage	12 Tons
Dammeroton, rooky	siston, rocky Pond reservoir areas. Very infined Slope			Alfalfa hay	3.5 Tons 3 Tons	
					Grass-legume hay Grass-clover	4.8 AUM
					Grass hay	3 Tons
					Corn silage	16 Tons
					Alfalfa hay	3.5 Tons

	Management	WOODLAND MANAGEMENT			
Soil name	concern	Rating	Reason	Vermont natural communities	
Vershire	Harvest equip operability:	Moderately suited	Slope	Northern Hardwood Forest, Mesic Red Oak-Northern Hardwood Forest,	



Soil Fact Sheet - Continued

Windsor County, Vermont

Rich Northern Hardwood Forest, Dummerston Harvest equip operability: Moderately suited Slope Hemlock Forest, Vershire Slope Road suitability: Poorly suited Temperate Acidic Outcrop, Dummerston Road suitability: Poorly suited Slope Temperate Acidic Cliff, Temperate Calcareous Outcrop, Vershire Erosion hazard (off-road): Moderate Slope/erodibility Temperate Calcareous Cliff Dummerston Erosion hazard (off-road): Moderate Slope/erodibility