

49D: Vershire-Buckland complex, 15 to 25 percent slopes

The Vershire component makes up 60 percent of the map unit. The natural drainage class is well drained. Water movement in the most restrictive layer is low. This component is on moderately steep hills on glaciated uplands. The parent material consists of loamy till. Depth to a root restrictive layer, bedrock, lithic, is 20 to 40 inches.

The Buckland component makes up 25 percent of the map unit. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is moderately low. This component is on moderately steep hills on glaciated uplands. The parent material consists of loamy basal till. Depth to a root restrictive layer, densic material, is 20 to 33 inches.

Important farmland classification: NPSL	Land capability: 4 e	Vermont Agricultural Value Group: 8
-----------------------------------------	----------------------	-------------------------------------

Vermont Residential Onsite Waste Disposal Group and Subgroup: IIIf

This unit is marginally suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. The depth to the seasonal high water table and the restricted depth to bedrock in some areas are the major limitations. On-site investigations can help avoid areas with limited depth to bedrock. Additional fill material may be needed in some areas in order to meet the separation distance requirement between the bottom of the leachfield and bedrock. A detailed, site-specific analysis with groundwater level monitoring and determination of induced groundwater mounding may be required to establish the suitability of this unit. Mound system construction and other site modifications are often necessary. On sloping sites, curtain drains can help lower the water table to an acceptable level.

PHYSICAL and CHEMICAL PROPERTIES								EDOCION EACTORS	
Soil name	Depth	Typical	Clay	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	EROSION FACTORS		
	(ln)	texture	(Pct)				Kw	Kf	Т
Vershire	0-5	FSL	4-18	4.5 - 6.5	0.6-2	1.0-4.0	.20	.20	2
	5-26	CN-FSL	4-18	4.5 - 6.5	0.6-2	0.5-3.0	.17	.28	
	26-36	UWB			0.01-20				
Buckland	0-8	L	5-10	5.6 - 7.3	0.6-2	3.0-8.0	.32	.32	3
	8-25	FSL	5-10	5.6 - 7.3	0.6-2	0.5-2.0	.37	.37	
	25-65	L	7-14	6.1 - 7.3	0.06-0.2	0.0-1.0	.49	.49	

WATER FEATURES								SOIL FEATURES	
Soil name	Hydrologic group	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric		
			Frequency	Duration	Frequency	Duration	soil?	Depth to bedrock (range in inches)	
Vershire	С		None		None		No	20-40	
Buckland	C/D	1.0-2.0	None		None		No		

	LAND USE LIMITAT	AGRICULTURAL YIELD DATA		
Soil name	Land use	Rating	Reason **	Crop name Yield / acre
Buckland	Dwellings with basements:	Very limited	Slope	Grass-legume hay 3 Tons
Vershire	Dwellings with basements:	Very limited	Slope	Grass-clover 4.8 AUM
Buckland	Dandanana'n ana	,	Clone	Grass hay 3 Tons
	uckland Pond reservoir areas: Very limited ershire Pond reservoir areas: Very limited	•	Corn silage 12 Tons	
versnire			Alfalfa hay 3.5 Tons	
				Corn silage 14 Tons
				Grass-legume hay 2.5 Tons
				Grass-clover 4 AUM
				Grass hay 3.5 Tons
				Alfalfa hay 3 Tons

	Management	WOODLAND MANAGEMENT			
Soil name	concern	Rating	Reason	Vermont natural communities	
Buckland	Harvest equip operability:	Moderately suited	Slope	Northern Hardwood Forest, Mesic Red Oak-Northern Hardwood Forest,	



Soil Fact Sheet - Continued

Windsor County, Vermont

Vershire	Harvest equip operability:	Moderately suited	Slope	Rich Northern Hardwood Forest,
Buckland	Road suitability:	Poorly suited	Slope	Hemlock Forest, Temperate Acidic Outcrop,
Vershire	Road suitability:	Poorly suited	Slope	Temperate Acidic Cliff,
Buckland	Erosion hazard (off-road):	Moderate	Slope/erodibility	Temperate Calcareous Outcrop, Temperate Calcareous Cliff
Vershire	Erosion hazard (off-road):	Moderate	Slope/erodibility	Temperate Galcareous Clili