

PeD: Peru fine sandy loam, 15 to 25 percent slopes

The Peru component makes up 70 percent of the map unit. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is moderately low. This component is on hills on glaciated uplands, mountains on glaciated uplands. The parent material consists of coarse-loamy basal till. Depth to a root restrictive layer, densic material, is 18 to 24 inches.

Important farmland classification: NPSL

Land capability: 4 e

Vermont Agricultural Value Group: 8

Vermont Residential Onsite Waste Disposal Group and Subgroup: IIIe

This unit is marginally suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. The depth to the seasonal high water table and slopes greater than 20 percent in some areas are the major limitations. A detailed, site-specific analysis is generally required. On-site groundwater level monitoring and determination of induced groundwater mounding is often necessary to establish the suitability of this unit. Curtain drains may help lower the water table to an acceptable level. There may be less-sloping areas within the unit that are suitable for siting a septic system, or, if feasible, cut and fill site modifications may produce an acceptable area within the unit. An erosion prevention and sediment control plan is required by the State for construction on sites over 20 percent slope.

PHYSICAL and CHEMICAL PROPERTIES

Soil name	Depth (In)	Typical texture	Clay (Pct)	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	EROSION FACTORS		
							Kw	Kf	T
Peru	0-6	FSL	2-10	3.5 - 6.5	0.1-14	4.0-13	.37	.37	3
	6-8	FSL	1-10	3.5 - 6.5	0.1-14	5.0-12	.37	.37	
	8-12	FSL	1-10	3.5 - 6.5	0.1-14	4.0-10	.43	.43	
	12-18	FSL	1-10	3.5 - 6.5	0.1-14	2.0-6.0	.37	.37	
	18-21	FSL	1-10	3.5 - 6.5	0.1-14	2.0-6.0	.43	.43	
	21-24	FSL	1-10	3.5 - 6.5	0.1-14	0.5-2.0	.55	.55	
	24-65	SL	1-10	3.5 - 6.5	0.01-1	0.0-1.0	.43	.43	

WATER FEATURES

SOIL FEATURES

Soil name	Hydrologic group	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric soil?	Depth to bedrock (range in inches)
			Frequency	Duration	Frequency	Duration		
Peru	C/D	1.3-2.5	None		None		No	---

LAND USE LIMITATIONS

AGRICULTURAL YIELD DATA

Soil name	Land use	Rating	Reason **	Crop name	Yield / acre
Peru	Dwellings with basements:	Very limited	Slope	Pasture	7 AUM
				Grass-legume hay	3.5 Tons
				Corn silage	16 Tons

WOODLAND MANAGEMENT

Soil name	Management concern	Rating	Reason	Vermont natural communities
Peru	Harvest equip operability:	Moderately suited	30-60cm to water table f >=6mos	Northern Hardwood Forest, Red Spruce-Northern Hardwood Forest, Hemlock Forest
Peru	Road suitability:	Poorly suited	Slope	
Peru	Erosion hazard (off-road):	Moderate	Slope/erodibility	