

29A: Grange very fine sandy loam, 0 to 3 percent slopes

The Grange component makes up 85 percent of the map unit. The natural drainage class is poorly drained. Water movement in the most restrictive layer is moderately high. This component is on depressions, drainageways, nearly level outwash terraces on river valleys. The parent material consists of loamy glaciofluvial deposits over sandy and gravelly glaciofluvial deposits. Depth to a root restrictive layer is greater than 60 inches.

Important farmland classification: Prime (b) **Land capability:** 4 w **Vermont Agricultural Value Group:** 3d

Vermont Residential Onsite Waste Disposal Group and Subgroup: IVa

This unit is generally not suited as a site for soil-based residential wastewater disposal systems, based on a review by the Natural Resources Conservation Service of criteria set forth in the Vermont 2007 Environmental Protection Rules. Excessive soil wetness in association with the minimal slope is the limiting condition. Prolonged periods of saturation at or near the soil surface do not allow for the proper functioning of septic systems.

PHYSICAL and CHEMICAL PROPERTIES							EROSION FACTORS		
Soil name	Depth (In)	Typical texture	Clay (Pct)	Soil reaction (pH)	Permeability (In/Hr)	Organic matter (Pct)	Kw	Kf	T
Grange	0-1	HPM	---	3.2 - 5.7	2-6	25-100	---	---	3
	1-6	VFSL	1-10	5.1 - 6.5	0.6-2	2.0-7.0	.43	.43	
	6-25	FSL	1-10	5.1 - 6.5	0.6-2	0.5-2.0	.43	.43	
	25-65	S	1-5	5.1 - 7.3	2-20	0.0-0.5	.02	.02	

WATER FEATURES						SOIL FEATURES		
Soil name	Hydrologic group	Depth to seasonal high water table (Feet)	Flooding		Ponding		Hydric soil?	Depth to bedrock (range in inches)
			Frequency	Duration	Frequency	Duration		
Grange	B/D	0.0-1.5	None		None		Yes	---

LAND USE LIMITATIONS				AGRICULTURAL YIELD DATA	
Soil name	Land use	Rating	Reason **	Crop name	Yield / acre
Grange	Dwellings with basements:	Very limited	Depth to saturated zone	Grass-legume hay	2.5 Tons
Grange	Pond reservoir areas:	Very limited	Seepage	Grass hay	3 Tons

WOODLAND MANAGEMENT				
Soil name	Management concern	Rating	Reason	Vermont natural communities
Grange	Harvest equip operability:	Poorly suited	<30cm to water table for >=6mos	Red Maple-Black Ash Swamp, Alder Swamp
Grange	Road suitability:	Moderately suited	Wetness	
Grange	Erosion hazard (off-road):	Slight		